Field Applicator
1.0.2 Release Notes

Updates

- Missing trips in the map will no longer occur.
- GPS trip point moved from the back corner to the back center of the implement.