



Field Applicator & Sensor Upgrade 3.0.0 Release Notes

Required Software

- Mirus version 5.0.0
- GNSS Plugin version 5.0.0

Required Actuator Firmware

- Version 7.58.5

Updates

- Initial release. Updated for Mirus 5.0 compatibility.